

800K Disk Eject INIT: Not Available for the Apple IIGS (11/94)

Revised: 11/21/94 Security: Everyone

800K Disk Eject INIT: Not Available for the Apple IIGS (11/94)

Article Created: 7 August 1990

Article Reviewed/Updated: 21 November 1994

TOPIC -----

I use the 800K Eject INIT in Macintosh systems. Is there is a similar program for the Apple IIGS?

DISCUSSION -----

There is no program for the Apple IIGS that provides the same function as the 800K Eject INIT. There were no reports of drive failures on the Apple IIGS using 800K disk drives, as there were with some Macintosh systems. Because of this, such a program is not necessary.

Article Change History:
21 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1990-94, Apple Computer, Inc.

Tech Info Library Article Number:5995